

600S UPDATE



Start with the 600S receiver unplugged from power & connect computer to 600S cable on Port A or Port B

Note: Port A & Port B are direct connect to the GPS board. Unlike the P300 the 600S has it's own port for RTK so if you have an RTK unit you can still update through either port and not switch the configuration first

Items you will need

1. Download from <http://ravenhelp.com/Product-Support/Guidance-and-Steering/GPS-Receivers.aspx> click on Software Updates & then click 600S.
2. USB to serial adapter.

RAVEN

GPS RECEIVER UPDATE RECOMMENDATIONS

DOES THE LAPTOP HAVE A SERIAL PORT?



KNOW YOUR COM PORTS

You will need to know which COM port your computer is using for the receiver connection in order to update using WinLoad. Use the instructions below to determine which COM port is being used

If your laptop computer has a serial port, you can connect it to the receiver using a straight-through serial cable. However, most newer laptops do not have a serial port for connecting with a receiver. For these computers, a USB-to- Serial adapter will be needed. Raven offers a supported adapter. Part number (524-0002-063).

HAVE ADEQUATE POWER

It is always recommended to have constant 12 volts to the receiver. If the receiver is running off of machine voltage, always have the machine running when applying the update. Any issues with voltage that occur during the update can cause the receiver to fail, after which it will need to be sent in for repair.

Some GPS engine updates can take 30 minutes or longer, so having a power supply for laptops is recommended over using just the internal batteries.

If your battery isn't outputting a full 12 volts you may not notice unless you measure it. The receiver will power up even if the voltage is under 10 volts. You will not only have issues with updating but also the functionality of the receiver.

Differential issues would occur.

Your computer COM Setup

1. Click on Start

2. Right Click on My Computer

3. Click on Properties

Installation:

1. Unzip the "RavenLoader_3.622_2.05.0013_1.22.010" file.
2. Connect the COM port on your PC to Port B of the Phoenix 300 using the supplied cable (115-0171-272). If you do not have a COM (9-pin serial) port on your pc, you will need to get a USB to Serial adaptor.
3. Set the baud rate to 19,200 on the Port B configuration screen on the receiver.
4. In the folder you extracted, run the Ravenloader.exe Program.
5. Click on "File" and then "New".
6. Click on "COM Port" in the top toolbar and then "settings".
7. Set the COM Port number to match the port number you are using on your PC. If you are using a USB to Serial adaptor, you may have to verify which COM port is assigned to the adaptor. Here's how to verify the COM port if needed:
 1. Right click on "My Computer"
 2. Left click on "Properties"
 3. Choose the "Hardware" tab.
 4. Select "Device Manager".
 5. Click on the plus (+) sign next to "Ports (COM & LPT)" Here you will see what the COM port number is.
8. Click the "OK" button.
9. Click the "Detect Receiver Type" button.
10. If updating the Raven front panel software, click the "Update Front Panel" button. This will update both the Raven software and Novatel software.

Windows 7 or Windows Vista screenshot

The screenshot shows the Windows 7 Control Panel window titled "Control Panel > All Control Panel Items > System". The address bar includes a search box labeled "Search Control Panel". The left sidebar contains the following links: "Control Panel Home", "Device Manager", "Remote settings", "System protection", and "Advanced system settings". The main content area is titled "View basic information about your computer" and displays the following system information:

- Windows edition: Windows 7 Professional
- System: Rating: 7.2 Windows Experience Index; Processor: Intel(R) Core(TM) i7 CPU 970 @ 3.20GHz 3.20 GHz; Installed memory (RAM): 18.0 GB; System type: 64-bit Operating System; Pen and Touch: No Pen or Touch Input is available for this Display
- Computer name, domain, and workgroup settings: Computer name: [blank]; Full computer name: [blank]; Computer description: [blank]; Domain: [blank]; Change settings
- Windows activation: Windows is activated; Product ID: [blank]; Change product key

A blue callout box with white text points to the "Device Manager" link in the sidebar, containing the text: "Click on Device Manager to get the COM Port settings".


See also:
Action Center
Windows Update
Performance Information and Tools

ask for genuine Microsoft software
Learn more online...


COM Port Setup

4. Click on Hardware

5. Click on Device Manager



6. Click on Ports




7. See what COM is being used by your computer


Note: You can confirm by temporarily unplugging the cable to see what COM disappears. Then you know that is the correct one

600S GPS UPDATE


Unzip the Update zip file into a folder on your computer that you downloaded from ravenhelp.com.
The results should look like: Note: filename may differ from what is shown



600S GPS UPDATE



600S GPS UPDATE



1.) Click on
"File" and then
"File Open"

600S GPS UPDATE

Note: filename may differ from what is shown below Note: .hex or .shex.

Organize ▾ Share with ▾ Burn New folder

★ Favorites

- Downloads
- Recent Places
- DatAnywhere

Libraries

- Documents
- Music
- Pictures
- Videos

Computer

- OSDisk (C:)
- Home Drive (G:)
- ATD Mapped Drive (H:)


Documents library

Firmware

Name	Date modified	Type	Size
OEM060700RN0000	7/11/2016 7:49 AM	SHEX File	11,560 KB
WinLoad	7/11/2016 7:49 AM	Application	6,123 KB

Double Click on OEMxxxxx.hex

600S GPS UPDATE



You should now see the file information within the WinLoad Program

Now click on the "Write Flash" button, wait a few seconds proceed to the next step.

600S GPS UPDATE



600S GPS UPDATE

The update will now begin

WinLoad - C:\Users\djs\Desktop\Winload\3902.hex

File Settings Help

Authorization Code:

Searching for card ... timeout in: 18 secs
Card Detected
V4.00 COM2 PXA250
Found platform: PXA250
Expecting platform: ARM
Changing Baud Rate to: 57600
Changing baud rate
baud rate changed
Initializing download

Write Flash
Run Script
Query Card
Abort

Card Properties
PSN:
Enclosure:
OSN:
HW Rev:

Hex File Properties
Platform: ARM
Type: APP
Version: 3.902

Target Card ID:
Boot Target Card ID:

COM: 10 Connect: BREAK Download: 57600

Once done it will show this bar which stays all the way to the right & the text shows "Done" & "Reset"

600S GPS UPDATE IS COMPLETE

Reset Power to the unit.

Open RFPSim program from your download then follow the procedure to do a FRESET




It is always good idea to enter the FRESET command into the GPS receiver so that the NVRAM table is synchronized to the memory mapping of this new firmware. Failure to perform this step could result in erratic performance, including the possibility that selected configurations will not be saved.

RAVEN

FRESET with RFPsim

1. Open RfpSim program
2. Connect serial connection
3. Select matching baud rate using the appropriate COM port. Port A – 19,200 or (115,200 if connected to Viper 4, E-Pro II, or connected with SmarTrax 7.4.56 or newer) & Port B – 115,200
4. Press the Connect button in upper left corner. Confirm data is streaming



FRESET WITH RFPSIM

1. CLICK ON BUTTON OPTIONS
2. SELECT BUTTON GROUP 4
3. CLICK FRESET
4. CLICK SEND
5. REBOOT THE RECEIVER IF IT DOESN'T BUT IT SHOULD REBOOT


NOTE: AFTER FRESET THE 600S DEFAULTS TO 9600 BAUD. THE CONFIGURATION ON THE NEXT PAGE IS REQUIRED TO SET THE RECEIVER BACK UP TO THE CORRECT BAUD RATES AND CONFIGURATIONS

The screenshot shows the RFP Sim v3.40.0.0 interface. The title bar reads "RFP Sim v3.40.0.0 - Button Group #4 - COM5 at 115200 BAUD is connected". The main window has several tabs: "ComPort", "BaudRate", "Logging Options", "Message Monitor Options", "Button Options", "RFP Options", and "more". The "Button Options" menu is open, showing a list of options: "Hide Buttons", "Button Group 1", "Button Group 2", "Button Group 3", "Button Group 4" (selected with a blue dot), and "Show Script Details" (checked with a blue checkmark). A red arrow points to the "Button Options" tab, and a yellow arrow points to "Button Group 4". Below the menu, there are several buttons: "BackLight", "Home", "Dis", and "Contrast". A green arrow points to the "F6 FRESET" button in the right-hand panel. The bottom panel shows a list of log messages starting with "09:18:54 \$GPGGA,141854.80,4333.0545106,N,09643.4906580,W,2,18,0.9,452.871,M,,04,0133". At the bottom of the window, there are buttons for "FRESET", "Send", "Pause", "Clear", "Send File", and "Add CkSum". A red arrow points to the "FRESET" button.

CONFIGURATION OF 600S

1. CLICK BUTTON OPTIONS
2. SELECT BUTTON GROUP 1
3. SELECT THE CONFIGURATION TO THE RIGHT

NOTE: ONLY SELECT THE CONFIG YOUR RECEIVER IS UNLOCKED FOR. IT WILL NOT FUNCTION WITH ANYTHING ELSE. THESE KEYS WILL SET UP THE CORRECT BAUD & CONFIGURATION. NO OTHER KEYS SHOULD BE SELECTED.



FRESET with RFPSim

1. Power Cycle the receiver
2. Allow the system to populate GPS information. You are done!

The screenshot shows the RFPSim v3.40.0.0 software interface. The main window displays a simulated GPS receiver screen with the RAVEN INDUSTRIES logo and STARLINK GPS branding. The screen shows a large green rectangular area, likely representing the GPS display. Below the screen are navigation buttons: Home, Diag, and Contrast. The interface also includes a menu on the right with options like Config SBAS, Config Sat. GS, Config Sling. GS, Config RTK, Autonomous GL1D, PortB Baud115200, PortA Baud115200, and imarTrax Message. A terminal window at the bottom displays a stream of NMEA sentences, including GPGGA, GPVTG, and GPZDA, indicating that the system is receiving GPS data.

```
10:38:51 92631 $GPGGA,153851.80,4333.0546507,N,09643.4907385,W,2,09,0.9,452.621,M,,06,0133
10:38:51 92647 $GPVTG,37.263,T,37.263,M,0.024,N,0.045,K,D
10:38:51 92741 $GPGGA,153851.90,4333.0546515,N,09643.4907385,W,2,09,0.9,452.622,M,,06,0133
10:38:51 92772 $GPVTG,61.968,T,61.968,M,0.003,N,0.006,K,D
10:38:52 92959 $GPGGA,153852.00,4333.0546518,N,09643.4907381,W,2,09,0.9,452.625,M,,07,0133
10:38:52 92990 $GPVTG,222.950,T,222.950,M,0.034,N,0.063,K,D
10:38:52 93021 $GPGGA,153852.10,4333.0546517,N,09643.4907378,W,2,09,0.9,452.623,M,,07,0133
10:38:52 93037 $GPVTG,113.836,T,113.836,M,0.022,N,0.041,K,D
10:38:52 93053 $GPGGA,153852.20,4333.0546530,N,09643.4907370,W,2,09,0.9,452.622,M,,07,0133
10:38:52 93068 $GPVTG,341.839,T,341.839,M,0.032,N,0.059,K,D
10:38:52 93131 $GPGGA,153852.30,4333.0546529,N,09643.4907381,W,2,09,0.9,452.619,M,,07,0133
10:38:52 93146 $GPVTG,317.528,T,317.528,M,0.020,N,0.037,K,D
10:38:52 93255 $GPGGA,153852.40,4333.0546531,N,09643.4907379,W,2,09,0.9,452.617,M,,07,0133
10:38:52 93287 $GPVTG,177.170,T,177.170,M,0.029,N,0.054,K,D
10:38:52 93349 $GPGGA,153852.50,4333.0546538,N,09643.4907378,W,2,09,0.9,452.617,M,,07,0133
10:38:52 93380 $GPVTG,1.992,T,1.992,M,0.016,N,0.029,K,D
10:38:52 93443 $GPGGA,153852.60,4333.0546539,N,09643.4907369,W,2,09,0.9,452.620,M,,07,0133
10:38:52 93474 $GPVTG,223.330,T,223.330,M,0.004,N,0.007,K,D
10:38:52 93552 $GPGGA,153852.70,4333.0546530,N,09643.4907389,W,2,09,0.9,452.617,M,,07,0133
10:38:52 93583 $GPVTG,268.230,T,268.230,M,0.006,N,0.012,K,D
10:38:52 93645 $GPGGA,153852.80,4333.0546532,N,09643.4907394,W,2,09,0.9,452.618,M,,07,0133
10:38:52 93677 $GPVTG,4.593,T,4.593,M,0.018,N,0.034,K,D
10:38:52 93739 $GPGGA,153852.90,4333.0546539,N,09643.4907390,W,2,09,0.9,452.614,M,,07,0133
10:38:52 93770 $GPVTG,125.046,T,125.046,M,0.023,N,0.043,K,D
10:38:53 93879 $GPZDA,153853.00,18,05,2016,,
10:38:53 93973 $GPGGA,153853.00,4333.0546501,N,09643.4907379,W,2,09,0.9,452.619,M,,03,0133
```