# Switch Pro Firmware Release Notes

## Version: 1.70

1. Require a master switch cycle before powering boom outputs for safety enhancement.
2. Fixed issue with distance accumulation seen with GPS Speed when traveling faster than 10 MPH.

## Version: 1.60

3. Added support for GPS speed over the CAN bus.

## Version: 1.50

4. Modified heartbeat reception to avoid errors if multiple consoles are in the system.
5. Stopped sending vol/min when the product is turned off.
6. Added valve_cal_2 functionality into fast close valve.
7. Fixed decimal shift issue on startup/restart of console.
8. Added valve advance feature.
9. Changed valve delay timeout from 30 seconds to 120 seconds.

## Version: 1.02

1. Fixed minor bugs with multi-console CAN support
2. Added Switch status to the boom status CAN message.
3. Fixed issue with rate shifting a decimal place when in metric and the field computer was restarted.

## Version: 1.01

1. Fixed bug with Radar Speed and pwm valve settings causing issues when used at the same time.

## Version: 1.00

1. Original release software.